



**Audi**

**Important!**

Please give copies to  
all your Audi Technicians

# Technical Bulletin

**Subject: Remote Transmitter Key Inoperable**

**Group: 57**

**Number: 05-02**

**Model(s): All-new A4, S4  
Sedan, Avant**

**2005 ► VIN: 8E\_5\_525414**

**Date: May 3, 2005**

## Condition

Locking or unlocking the doors using the remote transmitter is not possible with one or both keys (in some cases remote function is temporarily restored by switching ignition ON and OFF again).

May be caused by voltage loss due to contact problems within the remote.

## Production

New remote transmitter key supplied after VIN: 8E\_5\_525414.

## Service

- Replace remote transmitter keys with new Part No. as listed below.

## Parts Information



### Tip:

*Part numbers listed in this bulletin are for reference only. Always check with your Parts Dept. for the latest parts information.*

To read the part number, unfold the key

Old Part No:	New Part No:
8E0 837 220A INB	8E0 837 220F INB

## Warranty:



### Tip:

*NO diagnostic time will be allowed under Warranty.*