



Important! Technical Bulletin

Please give copies to
all your Audi Technicians

Vehicle Delivery Information

Subject: **Various Control Modules with Sporadic Diagnostic
Trouble Codes (DTCs) Stored in DTC Memory**

Group: **01**

Number: **05-02**

Model(s): **All-new A4, S4
(Avant, Sedan)**

2005 from VIN: 8E_5_400001 & 2006 Date: **Feb. 14, 2005**

Condition

Various Control Modules may have certain DTCs stored in memory.

Vehicle owner will not be aware of these faults.

Service

If any of the following DTC(s) exist during fault memory interrogation:

DTC	Control Module	Description
18111	Transmission Control Module (TCM) -J217-	Control unit reset
01794	Airbag Control Module -J234-	Control module incorrect Vehicle Identification Number (VIN) number
00852	Control Module -J401- for Navigation with CD-mechanism "Audi Navigation Plus"	Front loudspeaker(s)
00858		Connection between ZF-output radio to antenna amplifier
01030	Convenience System Central Control module -J393-	Central locking key button - driver side, lock
01031		Central locking key button - driver side, unlock

– Perform no further diagnosis or repair on these DTC(s).

◆ Audi is currently working on a technical Solution to address these DTC(s).

 **Tip:**

No Diagnostic time will be allowed for Warranty.

– Initiate Hotline Channel Ticket for above DTC(s).

– Complete diagnosis and repairs on DTC(s) not listed in above table.

– Erase DTC memory.