



Audi

Important!

Please give copies to
all your Audi Technicians

Technical Bulletin

Subject: Airbag, Replacement Interval Change

Group: 69

Number: 05-02

Model(s): All with Airbags

All MY

Date: Feb. 7, 2005

Condition

Since introduction on Audi vehicles, replacement of Airbag units has been recommended after a period of between 10 and 15 years.

Service

In response to any Customer inquiries regarding Airbag unit Replacement intervals:

Please inform the Customer that Audi no longer recommends Airbag replacement at these or other intervals.