

**Audi**

Please give copies to
all your Audi Technicians

Technical Bulletin

Subject: **Satellite Radio -R146-, Interference with Tire Pressure Monitoring System or Audi Navigation Plus**

Group: **91**

Number: **05-01**

Model(s): **A4, S4 (Sedan, Avant), Cabriolet
A6, allroad, TT**

**2005
2005**

Date: **Feb. 4, 2005**

Condition

Satellite Radio Tuners Part Nos: 8E0 057 593 (Sirius) and 8E0 057 593A (XM)

- Interfere with Tire Pressure Monitoring Systems (TPMS).
- DO NOT function at all with Audi Navigation Plus.

These satellite tuners are OK to use in vehicles without TPMS or Audi Navigation Plus.

Service

Satellite tuners, installing or replacing

Vehicles equipped with TPMS and/or Audi Navigation Plus:

- Must use Satellite Tuner Part Nos: 8E0 057 593D (Sirius) or 8E0 057 593E (XM).

Vehicles not equipped with TPMS and/or Audi Navigation Plus:

- Order existing stock Part No: 8E0 057 593 (Sirius) or 8E0 057 593A (XM) until stock is depleted.

If these Part Nos. are not available:

- Part Nos: 8E0 057 593D (Sirius) or 8E0 057 593E (XM) can be installed.



Tip:

Part numbers listed in this bulletin are for reference only. Always check with your Parts Dept. for the latest parts information.